







LC105M

	LC105
Torch (Machine 7.5m) (1pc)	PTM-101A-CX-7M5A
Torch (Machine 15m) (1pc)	PTM-101A-CX-15MA
Positioning tube (1pc)	W0300603R
Head (1pc)	W0300619R
Insulation Kit (blister 1pc)	W03X0893-71R
Cable (7.5m) (1pc)	W0300621R
Cable (15m) (1pc)	W0300623R
Connector (1pc)	W03X0934-8R



	Electrode (blister 5pcs)	Gas Distr. (blister 2pcs)	Tip (blister 5pcs)	Retaining Cap (blister 1pc)	Shield Cap (blister 2pcs)
Cutting process					
40A	W03X0893-60A	W03X0893-70R	W03X0893-61A	W03X0893-66A	W03X0893-68A
60A	W03X0893-60A	W03X0893-70R	W03X0893-62A	W03X0893-66A	W03X0893-68A
80A	W03X0893-60A	W03X0893-70R	W03X0893-63A	W03X0893-66A	W03X0893-68A
100A	W03X0893-60A	W03X0893-70R	W03X0893-64A	W03X0893-66A	W03X0893-68A
Gouging	W03X0893-60A	W03X0893-70R	W03X0893-65A	W03X0893-66A	W03X0893-69A

LC105M (машинный резак) на данном резаче возможно применение как расходных элементов для неконтактного реза, так и для контактного реза, хоть и в машинном варианте контакта с деталью не происходит.

Перечень расходников:

- Электрод W03X0893-60A
- Газовый диффузор W03X0893-70R единый.
- Сопла W03X0893-61A-62A-63A-64A на ток 40, 60, 80 и 100A + Удерживающий колпачок W03X0893-66A + Защитный колпачок W03X0893-68A.
- Сопло W03X0893-65A на весь диапазон рабочих токов для строжки.